

## American Diner, serving classic USA eats in Manchester's Northern Quarter

A busy city centre restaurant with low level extraction near neighbouring properties



### Issue

This city centre restaurant, in the heart of Manchester's bustling and metropolitan Northern Quarter, had low level extraction, causing problems for neighbouring properties.

### Solution

High efficiency Coil Filters were installed in the canopy, capturing 95% of grease particles. Then, our Electrostatic UV was installed into their ductwork, keeping extraction ducts virtually grease-free.



### Result

Dramatically reduced the grease build up in the system. From the relatively clean coils on the back of the filter, only a small amount of grease had penetrated through - as promised. The ESP UV system had eradicated most grease, grime and germs you would normally find downstream in the ductwork.

[plasma-clean.com](http://plasma-clean.com) · [ask@plasma-clean.com](mailto:ask@plasma-clean.com) | +44 (0)161 870 2325  
Earl Business Centre, Dowry Street, Oldham, OL8 2PF

[f](https://www.facebook.com/PlasmaClean) [@PlasmaClean](https://www.instagram.com/PlasmaClean) [in](https://www.linkedin.com/company/Plasma-Clean-LTD) /Plasma-Clean-LTD

