

The Harpers chain have a well-deserved reputation throughout the UK

Planning permission required this York city site to have suitable Grease and Odour Control in place



Issue

When opening a new outlet in York, one of the planning conditions was to have a suitable grease and odour control system in place. The shop is located within a shopping precinct, with residential properties nearby.

Solution

Given the type of cooking and the sensitive site location, a Combined Electrostatix with UV-C unit was installed. Combining electrostatic precipitation with UV-C light technology resulted in the highly-efficient removal of grease and odour in a single unit.



Result

Six months post-installation, the outlet side of the Electrostatix and UV-C system, together with the downstream ductwork, remains clean and free from grease.

plasma-clean.com · ask@plasma-clean.com | +44 (0)161 870 2325
Earl Business Centre, Dowry Street, Oldham, OL8 2PF

Facebook Twitter @PlasmaClean LinkedIn /Plasma-Clean-LTD

